

## **VINYL APPLICATION LEGEND**

Not sure where to start with your vinyl sheets? Don't fret! Each sheet is marked with a symbol that matches the application guidelines in our user guide. Let's get crafting — it's as easy as A, B, C! �� 🔆

Symbol	Type of Vinyl	Fabric	Guidelines
Α	Adhesive – Glow In The Dark		
В	Adhesive – Sunlight Sensitive		
С	Adhesive – Temperature Activated Cold		
D	Adhesive – Temperature Activated Hot		
Е	Adhesive/Sticker/Permanent		
U	Heat Transfer – Hot Peel	Polyester and Cotton	Transfer pressure: Medium Temperature: 150°C – 160°C Time: 8 – 12 Seconds Remove carrier: Hot
V	Heat Transfer – Warm Peel	Polyester and Cotton	Transfer pressure: Medium Temperature: 150°C – 160°C Time: 8 – 12 Seconds Remove carrier: Warm
W	Heat Transfer – Cold Peel	Polyester and Cotton	Transfer pressure: Medium Temperature: 150°C – 160°C Time: 8 – 12 Seconds Remove carrier: Cold
X	Heat Transfer – Flock	Polyester and Cotton	Transfer pressure: Medium Temperature: 150°C – 160°C Time: 10 Seconds Remove carrier: Cold
Υ	Heat Transfer – Sunlight Sensitive	Polyester and Cotton	Transfer pressure: Medium Temperature: 140 – 160°C Time: 8 – 15 Seconds Remove carrier: Cold
Z	Heat Transfer – Glow In The Dark	Polyester and Cotton	Transfer pressure: Medium Temperature: 150°C – 160°C Time: 10 Seconds Remove carrier: Cold